



Table of Contents

CHAPTER 27 ~ Bridge – Batch Plotting

EFLHD Batch Plotting.....27-1,2



BATCH PLOT GUIDELINES

To Plot a series of drawings or total project
Using Cell Name: "**Batch plot area**"

Step 1: Place Cell "**Batch plot area**" over borders you want to print.
Place them in the order you want.

Step 2: Initiate Batch Print from "File" pull down menu.

Step 3: Select "**Print Area**"

Step 4: Select "**Specifications**" button

Step 5: Select method "**Cell**" then hit OK.

Step 6: Select "**Specifications Properties**"

Select "**Cell**"

Check off:

- ✓ **Master File**
- ✓ **References**
- ✓ **Process Multiple Boundary Elements (at bottom of menu)**

Type in "**Batch plot area**" for cell name

Hit **OK**

Step 7: Under "**Edit**" menu, Select "**Add Active File**"



Note: may add more than one file

Step 8: Select **Print**, verify pen table and print drive and hit **OK**

PLOT DRIVE INSTRUCTIONS:

Highlight "Printer"

Select **"Specifications"** button

Hit **"Driver"** button

Locate following:

M:\cadd\PLOTDRV\e_lpt1.plt

Hit **"OK"**

PEN TABLE INSTRUCTIONS:

Highlight "Display" and double click

Select **"Specifications"** button

Hit **"Browse"** button

Locate following:

M:\cadd\PENTABLE\LABELS.TBL

Hit **"OK"**

Step 9: Hit **OK** thru any other menu that pops up.

Step 10: Save job in projects folder. File name is in format
name.job